

From glowbugs@theporch.com Mon Jan 15 21:56:35 1996
Return-Path: glowbugs@theporch.com
Received: from uro (localhost.theporch.com [127.0.0.1]) by uro.theporch.com
(8.7.3/AUX-3.1.1) with SMTP id VAA00310; Mon, 15 Jan 1996 21:35:07 -0600 (CST)
Date: Mon, 15 Jan 1996 21:35:07 -0600 (CST)
Message-Id: <199601160335.VAA00310@uro.theporch.com>
Errors-To: ws4s@midtenn.net
Reply-To: glowbugs@theporch.com
Originator: glowbugs@theporch.com
Sender: glowbugs@theporch.com
Precedence: bulk
From: glowbugs@theporch.com
To: Multiple recipients of list <glowbugs@theporch.com>
Subject: GLOWBUGS digest 77
X-Listprocessor-Version: 6.0c -- ListProcessor by Anastasios Kotsikonas
X-Comment: Please send list server requests to listproc@theporch.com
Status: 0

GLOWBUGS Digest 77

Topics covered in this issue include:

- 1) Drake Receivers for Sale
by Kim Herron <kherron@voyager.net>
- 2) RMS (was dropping filament voltage)
by mjsilva@ix.netcom.com (michael silva)
- 3) Help Unsubbing Please...
by POLARIS@VAX1.MANKATO.MSUS.EDU
- 4) .
by KE8NEfix@aol.com

Date: Mon, 15 Jan 1996 10:00:38 -0500
From: Kim Herron <kherron@voyager.net>
To: Boatanchors@theporch.com
Cc: Glowbugs@theporch.com
Subject: Drake Receivers for Sale
Message-ID: <199601151500.KAA13029@vixa.voyager.net>

Hi Gang,

I have decided that it is time to thin the collection of Drake Equipment that has grown around me. I have a 2B, R4A and R4B for sale. I'd like \$90.00 for the 2B, \$135.00 for the R4A and \$235.00 for the R4B. These prices include shipping. I'm in kind of a hurry this morning and so I don't have the time to put a lengthy description of them in here, but you may call me on the phone [616-677-3706], or e-mail me and I'll be happy to answer all

the questions that you have. This I will tell you, the 2B is in nice shape on the front panel, works well. The R4B is superb in and out and works excellent, and the R4A works pretty good but could stand an alignment. Let me know

Thanks,

KIM

Date: Mon, 15 Jan 1996 13:46:53 -0800
From: mjsilva@ix.netcom.com (michael silva)
To: glowbugs@theporch.com
Subject: RMS (was dropping filament voltage)
Message-ID: <199601152146.NAA21911@ix9.ix.netcom.com>

Hi gang,

Barry Ornitz pointed out a goof in my comments regarding dropping tube heater voltages by using a diode. While removing every half-cycle will produce half the heating -power-, that does -not- equate to an equivalent of 60 volts (pause to give myself an I-knew-that slap...). Voltage goes as the square root of power, so the equivalent voltage produced by half-wave rectifying 120 volts is $120 * \sqrt{0.5}$, or 85 volts. It is this value that should be used in determining any needed additional dropping resistance (the original quest was for 50 volts). Hope I didn't cause any pyrotechnics out there.

73,
Mike, KK6GM

Date: Mon, 15 Jan 1996 17:25:26 -0600 (CST)
From: POLARIS@VAX1.MANKATO.MSUS.EDU
To: glowbugs@theporch.com
Subject: Help Unsubbing Please...
Message-ID: <01I01PMSHMNM009M5J@VAX1.MANKATO.MSUS.EDU>

Hello,
Sorry to waste any further space here, but I really have not been at all successful unsubscribing to this list using the address given in all of the message headers. Would some kind soul help me to unsub?

Thanks very much,

David Forsyth

Date: Mon, 15 Jan 1996 18:28:21 -0500
From: KE8NEfix@aol.com
To: glowbugs@theporch.com
Subject: .
Message-ID: <960115182818_42769851@emout04.mail.aol.com>

suspend

End of GLOWBUGS Digest 77
